CITY OF JACKSONVILLE DEPARTMENT OF PUBLIC WORKS ENGINEERING DIVISION CONSTRUCTION CHANGE ORDER

Change Order No.	Two (2)	Date November 19, 2014 Revised
Description of Project	Mosquito Control Roof Replacement and Renovations	
Name of Contractor	Lynn Lee Construction Group, Inc.	
Contractor's Address	25 Knight Boxx Road #7303, Orange Park, FL 32065	
Contract No. 9526-06		
Account No. See attac	hed Original Contract	\$89,828.22
+ Previous Change Order 1 \$2,043.75 + Change Order No. 2 \$136,927.71 *See attached appendix for additional listings. TOTAL REVISED CONTRACT \$228,779.68 *7228,779.68		
Bid Number JCF-0039		April 25, 2014
<u> </u>		April 5, 2015
		August 26, 2014 August 6, 2015
In compliance with General Conditions of above-referenced contract, CONTRACTOR and OWNER do both hereby agree that the CONTRACTOR shall make the following changes, additions or deletions to the Work specified in the plans and specifications: See attached. Add 345 non-compensable calendar days to construction completion and contract expiration dates. Justification: See attached.		
The Issuing Authority has	looked over cost and pricing data for this change order	er and has determined that this change order is
necessary and all costs are		
Accepted for Contractor	Lynn Lee Construction Group Construction, Inc.	
Signed	Attest Levi	West
Title and	There I Title Ira	nearing Contract spacefulist
Date 11. 21	. 2014 Date	11-21-14.
	Authority By Thomas G. N	McKnight Date Overment Construction Manager
Signed.	Public Brildings By	12/1/1+
Using	Division	v/Department Head Date
Onef, Engineering & Caps	tyriction Mgmt Div Date Assistant	
X\ (2)	12/3/14/2	A M
Director of Public Works	Date Mayor	un Bouling Date
May her cafer/ny James RIE Call Janes		
Chief of rocurement Date Corporation Secretary		
Director of Finance Date Karen Bowling		
	9526-06	Chief Administrative Officer
	BB.	For: Mayor Alvin Brown Under Authority of:
	a de	Executive Order No. 2013-04
	V ^v ·	

SUBJECT: MOSQUITO CONTROL FACILITY RENOVATIONS "JSEB"

BID# JCF-0039-13

OPENDATE: 4/30/2013

GENERAL GOVERNMENT AWARDS COMMITTEE KIND AND BASIS OF CONTRACT: **JSEB SET-ASIDE** AGENCY: **PUBLIC WORKS** BASIS OF AWARD: TOTAL LUMP SUM BASE BID TO THE LOWEST RESPONSIVE, RESPONSIBLE BIDDER NUMBER OF BIDS INVITED NUMBER RECEIVED **OTHER** 11 0 SUMMARY OF BIDS AND RECOMMENDED ACTIONS: Subject bid was administratively awarded on 07/30/13 to LynnLee Construction Group, Inc., in the amount of \$89,828.22; Change Order #1 was administratively awarded in the amount of \$2,043.75. Recommend approval of Change Order #2 to LynnLee-Construction Group, Inc., in the amount of \$136,927.71 for a revised maximum indebtedness to the city not-to-exceed \$228,799.68. Funding for this award to be encumbered by account(s): PWCP32BPB519-069505-PW0752-01- \$3,745.42; PWCP32CPB519-06505-PW0752-01- \$113,926.92; PWCP31PPB519-06505-PW0752-01- \$4,073.08; PWCP32CPB519-06505-PW0677-01- \$15,182.29 to be executed by contract amendment through Office of General Counsel. Attachments: Recommendation Memo, Change Order, Previous Award RESPECTFULLY SUBMITTED: MARILYN LÁIÐLER GORY PEASE, CHIEF PROCUREMENT DIVISION William J. Joyce, P.E., Chief, Engineering and Construction Management Division CONCURRENCE BY: (ALL AWARD ACTIONS SUBJECT TO LAWFULLY APPROPRIATED FUNDS) ACTION OF GGAC COMMITTEE ON RECOMMENDATIONS ABOVE MEMBERS APPROVING __ -___ MEMBERS DISAPPROVING DATE: OTHER: ACTION OF AWARDING AUTHORITY DATE: _ APPROVED DISAPPROVED OTHER __

SIGNATURE OF AUTHENTICATION
Karen Bowling
Chief Administrative Officer
For: Mayor Alvin Brown
Under Authority of:
Executive Order No. 2013-04

FORM GB-108, Revised 12/2007

NET

NET

NBR

MASTER ITEM DESCRIPTION

QUANTITY UOM UNIT COST

ADDITION

DELETION TOTALS

UNFORSEEN CONDITIONS

The original scope was to replace the roofing system and interior ceiling tiles and to paint the newly installed exterior surfaces exposed to view. Once construction started a Stop Work Order by the Building Inspection Division city inspector (city inspector) required that other deficiencies be addressed.

1 MOLD REMEDIATION AND REPAIR DRY WALL

1.000 LS

\$4,365.98

\$4,365.98

JUSTIFICATION: After removing all furniture to start initial project unforeseen damages were discovered caused from the leaking roof and failure of existing septic tank which caused flooding to existing building. Mold remediation and dry wall repair must be performed before tenants can return to the facility

2 DRAINFIELD AND SEPTIC TANK

1 LS

\$12,137.70

\$12,137.70

REPLACEMENT

JUSTIFICATION: After removing all furniture to start initial project unforeseen damages were discovered from the roof leaking and numerous events of water backing up & flooding the building due to inoperable 20 yr. old septic tank system which has failed. According to the city inspector the facility must be brought up to the current Florida Building Code before occupants can return, which means replacing the failing septic system.

3 REPLACE AC COMPRESSER AND DUCT SYSTEM

1.000 LS

\$31,451,30

\$31,451,30

REPLACEMENT

JUSTIFICATION: After removing all existing ceiling grids the city inspector placed a STOP WORK ORDER on the project due to improper spacing. The city inspector indicated the roof system must be made current according to the Florida Building Code. The existing duct system was damaged and needed to be removed in order to install the new roofing system. Because of its age and condition, it could not be reinstalled. It was then decided to replace the existing 22 year old+ system while all the ceiling grids had been removed.

4 REPLACE URINALS

1.000 LS

\$4,412.78

\$4,412.78

JUSTIFICATION: After removing all furniture to start initial project unforeseen damages were discovered from the roof leaking and numerous events of water backing up & flooding the building due to inoperable 20 year old septic tank. It was discovered the plumbing is unusable due to rusted drain lines and must be replaced during the installation of the new septic system according to the city inspector this must be done in order for the building to be in compliance.

5 REPLACE ROTTEN WOOD AS NEEDED

1.000 LS

\$493.35

\$493.35

ON EXTERIOR WEST SIDE OF BUILDING.

NET

NET

NBR

MASTER ITEM DESCRIPTION

QUANTITY UOM UNIT COST

ADDITION

DELETION TOTALS

JUSTIFICATION: After removing all existing ceiling grids the city inspector placed a STOP WORK ORDER on the project due to improper roof member spacing the city inspector indicated the roof system must be made current according to the Florida Building Code meaning structurally increasing roofing members which increases the load also the exterior walls are rotted and must be replaced to support the roof system per the city inspector.

6 ADA EXTERIOR DOOR REPLACEMENT (10 INCLUDES

1.000 LS

\$19,610.51

\$19,610.51

HARDWARE AND TRIM AND CONCRETE WORK AT EACH ENTRANCE TO ALLOW PROPER SLOPE AT EACH

JUSTIFICATION: After removing all furniture to start initial project unforeseen Damages & issues were discovered caused from the leaking the city inspector immediately placed a STOP WORK ORDER on the project due to obvious ADA issues which must be addressed in order to obtain a certificate of occupancy per the city inspector the clients can't re-enter the building under these circumstances. Therefore, it is imperative to make sure the building is in compliance according to the Florida Building Code.

7 WINDOW AND VINYL REPLACEMENT

1 LS

3,443.58

\$3,443.58

JUSTIFICATION: After removing all existing ceiling grids the city inspector placed a STOP WORK ORDER on the project due to improper roof member spacing the city inspector indicated the roof system must be made current according to the Florida Building Code by structurally increasing the roofing members which increases the load weight the rotted windows are part of the exterior walls which are rotted also and must be replaced per the city inspector to be in compliance.

8 CAULK AWNING LEAKS

1.000 LS

\$439.87

\$439.87

JUSTIFICATION: The city inspector immediately placed a STOP WORK ORDER on the project after discovering unforeseen issues due to water intrusion. The awnings are not properly caulked permitting water intrusion which has caused the exterior walls to become rotted and must be caulked to prevent damages to the new proposed wall installation.

10 FIX ADA DEFICIENCIES IN CLASSROOM

1.000 L\$

\$1,661.76

\$1,661.76

BATHROOM

JUSTIFICATION: After removing all furniture to start initial project unforeseen Damages & issues were discovered the city inspector immediately placed a STOP WORK ORDER on the project due to obvious structural and ADA issues which must be addressed in order to obtain a certificate of occupancy such as(Doors, Toilets Grab Bars Soap &Paper Towel Dispensers) it is imperative to make sure the building is in compliance according to the Florida Building Code

9 PAINT INTEROR WALLS

1.000 LS

\$5,913.88

\$5,913.88

CHANGE ORDER NO. 1 11/24/2014

NET

NET

NBR

MASTER ITEM DESCRIPTION

QUANTITY UOM UNIT COST

ADDITION

DELETION TOTALS

JUSTIFICATION: After removing all existing ceiling grids the city inspector placed a STOP WORK ORDER on the project due to improper roof member spacing the city inspector indicated the roof system must be made current according to the Florida Building Code meaning structurally increasing roofing members which increases the load also the exterior walls are rotted and must be replaced to support the roof system per the city inspector. Interior walls have been replaced with demolition that must be repainted. Since all furniture has been removed from the facility and being housed in a POD this is the opportunity to paint the remaining interior walls while the property is vacant. otherwise the property must be vacated once again during some other time frame which is even more costly.

NET TOTAL UNFORESEEN CONDITIONS:

\$83,930.71

\$0.00

TOTAL UNFORESEEN CONDITIONS:

\$83,930.71

ADDITIONAL SCOPE

11 ADD STRUCTURAL FRAMING TO EACH

1.000 LS

\$52,997.00

\$52,997.00

TRUSS AS PER NEW PLANS. DEMO EXTERIOR WALLS, PANELING, DRYALL AND OLD

INSULATION. FRAME IN CMU WALL &

REMOVE WINDOW UNIT A/C SYSTEM. ADD

NEW DRYWALL AND WATERPROOF.

ADD THERMAL BARRIER

JUSTIFICATION: The replacement roof system did not meet code. During inspection, the inspector for the Building Inspection Division advised that in addition to additional structural framing to the new truss, the exterior wall would also need to be addressed in order to support the new roofing system. Structural changes required to meet code, ADA and safety for project.

NET TOTAL ADDITIONAL SCOPE

\$52,997.00

\$0.00

\$0.00

TOTAL ADDITIONAL SCOPE

\$136,927.71

NET TOTAL CHANGE ORDER #2
TOTAL CHANGE ORDER #2

ψ100,32.

\$136,927.71

\$52,997.00