Equal Opportunity Employer

DEPARTMENT OF PUBLIC WORKS

Building Inspection Division



June 25, 2001

MEMORANDUM

BULLETIN G-16-01

To: All Permit Applicants

From: Thomas H. Goldsbury, P.E., C.B.O.

Chief, Building Inspection Division

Subject: Slab Repair and Replacement Information

When existing slab work is disturbed it shall be re-treated with termicide per the manufacturers recommendation. Slab repair over 200 square feet shall be provided with a retreat certificate supplied by the pest control contractor and a slab inspection is required.

For slabs repairs less than 200 square feet re-treatment is required but no slab inspection shall be required from this division.

Structural slab work of any size shall require treatment and inspection.

If you have any questions, please contact the Building Inspection Division at 630-1100.

THG/gs

cc: James R. Schock, P.E., C.B.O.

Public Works

