
DEPARTMENT OF PUBLIC WORKS

140221



July 16, 2015

MEMORANDUM

TO:

James R. McCain, Jr.

Corporation Secretary/Assistant General Counsel

THROUGH:

Gerald Behrendt, City Comptroller

FROM:

Thomas G. McKnight - Thomas G. McKnight

Capital Improvement Construction Manager

SUBJECT:

Ft. Caroline Pool Repairs

Contractor: The Rose Group, LLC

Contract No: 9510-07

Forwarded herewith for execution is Change Order No. 1 for subject project.

Original Contract Amount\$197,000.00

Previous Change Order No. 0.....\$0.00

Change Order No. 1\$12,287.50

Total Revised Contract Amount\$209,287.50

Account NumberSee attached

This office recommends the Change Order be approved by your office, the Office of General Counsel, and Mayor Brown, in accordance with Executive Order No. 13-05.

Attachments: 1. Change Order

2. Back-up Information

3. Legal Request Memorandum

TGM:lw

CIPW15000047

CHANGE ORDER TRACKING SHEET

Description of Project	Fr Caroline	Pool Repairs	
Change Order Number	/	PLEASE KEEP THIS FORM WITH	
Contract Number	95/0-07	THE ATTACHED CHANGE ORDER	

Action	Date Received	Date Signed	Date Forwarded	Signature	Days
Date Initiated	N/A	N/A	6/25		
Α			,		ļ
Contractor Execution		6/30		71 - A	
Construction Management	7/6		<u>.</u>		<u> </u>
Using Agency					
JEA (if applicable)					
City Engineer		1/9			
C/O Review	7/.0	7/10			
Director of Public Works	7/15	7/15			
Admin/Finance Clerk	7/20	7/20		RAM	
O Buyer	7/21	7 21	•	J	
1 Chief of Procurement					
2 Director Finance	7/27	27/27	,	3	
Asst. General Counsel	-				
4 CAO/Mayor					
Asst. General Counsel					
Total Processing Days:					<u> </u>

Attention Change Order reviewers and signatories:

Please assist in expediting this change order by reviewing, signing, and forwarding immediately to the next step. Thank you in advance for your efforts to reduce contract change order processing times.

James M. Robinson, P.E. Director of Public Works

CITY OF JACKSONVILLE DEPARTMENT OF PUBLIC WORKS ENGINEERING DIVISION CONSTRUCTION CHANGE ORDER

Date

June 16, 2015

Change Order No.

One (1)

Description of Project Fort Caroline Pool Repairs
Name of Contractor The Rose Group, LLC
Contractor's Address 2933 N. Myrtle Avenue, Suite 101, Jacksonville, Florida 32209
Contract No. 9510-07
Account No. PWPB165-04603AFA013-01 Original Contract \$197,000.00
+ Previous Change Orders 0 \$0.00 + Change Order No. 1 \$12,287.50 *See attached appendix for additional listings.
TOTAL REVISED CONTRACT \$209,287.50 Bid Number JCF-0011-14 Construction Completion Date July 1, 2014
Revised Construction Completion Date October 22, 2014 October 29, 2014
Revised Contract Expiration Date August 31, 2015
In compliance with General Conditions of above-referenced contract, CONTRACTOR and OWNER do both hereby agree that the CONTRACTOR shall make the following changes, additions or deletions to the Work specified in the plans and specifications: See attached. Add 113 and 306 non compensable calendar days to construction completion and contract expiration dates, respectively.
Justification: See attached.
The Issuing Authority has looked over cost and pricing data for this change order and has determined that this change order is necessary and all costs are reasonable.
Accepted for Contractor The Rose Group, LLC Signed Attest X
Title ADA(NISTRATOR) Title > Pres.
Date Date Date Date Date Date Date Date
· · · · · · · · · · · · · · · · · · ·
Issuing Authority Thomas G. McKnight Capital Improvement Construction Manager Signed Public Buildings W By Public Buildings W By
Signed Construction Management By Thomas G. McKnight Capital Improvement Construction Manager Signed Public Buildings W By Div/Department Head Date Date Date Div/Department Head Date Date Date Div/Department Head Date Date Div/Department Head Date Date Div/Department Head Date Date Div/Department Head Date Date Div/Department Head Date Date Div/Department Head Date Date Div/Department Head Date Date Date Date Date Date Date Date
Using Division DiviDepartment Head Date By Sold Date Date Date Date Date Date Date Date
Chief, Engineering & Construction Ment Div Date Assistant Counsel Date
7/5/15 Damy Morena 1/29/19
Director of Public Works Date Mayor
Chief of Procurement Date Corporation Secretary Date
Chief of Frocurement Date Corporation Secretary Date
Director of Finance Date
9510-07 Chg Ord 1

SUBJECT:

FT. CAROLINE POOL REPAIR

BID# JCF-0011-14

OPENDATE: 2013-10-22

GENERAL GOVERNMENT AWARDS COMMITTEE

KIND AND BASIS OF CONTRACT:

CONSTRUCTION FIXED- JSEB SET-ASIDE

AGENCY:

PUBLIC WORKS

BASIS OF AWARD: LOWEST RESPONSIVE, RESPONSIBLE BIDDER-LUMP SUM BASE BID

NUMBER OF BIDS INVITED

3 NUMBER RECEIVED

1 OTHER

0

FORM GB-108, Revised 12/2007

SUMMARY OF BIDS AND RECOMMENDED ACTIONS:

Subject bid was administratively awarded on 12/02/13 to The Rose Group, LLC., in the amount of \$197,000.00; Award amended on 12/09/13 to correct vendor name.

Recommend approval of Change Order #1 to the Rose Group, LLC.,(contract #9510-07) in the amount of \$12,287.50. Total revised award amount not-to-exceed \$209,287.50.

Funding for this award to be encumbered by account: PWPB165-04603-AFA013-01 to be executed by contract change order through Office of General Counsel.

Attachments: Recommendation Memo, Change Order, Basis of Award, Previous Awards

BUYER: Marly RESPECTFULLY SUBMITTED:

K.	MARILYN LAIG)LER	•	PROCI	REMENT DIVISION	
	CONCURRENCE BY:	William J. Joyce, P	.E., Chief, Engine	ering and Const	ruction Management Divis	ion
			•			
		AWARD ACTIONS SI				
	MEMBERS APPROVIN	IG 3 MEMB	ERS DISAPPROVI	NG	DATE:	
	7	<u> </u>			OTHER:	
	Alle					
	Firms PIME				1 .	
	ACTION OF AWARDIN	GAUTHORITY		DATE:	1/06/19	
$\sqrt{\Lambda}$	APPROVED		DISAPPROVE	D		
Į ()	OTHER	\cap		-	Sam E. Mousa Chief Administrative Office	ter.
	SIGNATURE OF AUTH	IENITICATION \	MILIAGAS	Neuren	For: Mayor Lenny Curry	
	SIGNATURE OF AUTH	IENTICATION_	SANTATA .	VIVVIEW	Under Authority of: Executive Order No. 201	 5-05

NET

NBR MASTER ITEM DESCRIPTION QUANTITY UOM UNIT COST ADDITION NET DELETION TOTALS

NEW ITEMS -

UNFORESEEN CONDITIONS:

2 REPAIR LEAK IN 4" SCUM GUTTER LINE, 1 LS \$5,158.00 \$5,158.00

PRESSURE TEST THE REPAIR

JUSTIFICATION: A pressure check identified that there was a leak in the scum gutter line. After localizing the leak the contractor had to remove sections of the concrete pool deck until the leak was located. After the repair, the contractor was to compact with suitable fill material and replace concrete to match existing texture of the deck.

TOTAL UNFORESEEN CONDITIONS \$5,158.00

ADDITIONAL SCOPE:

3 CLEAN AND INJECT EPOXY IN LARGE CRACK IN 1 LS \$1,375.00 \$1,375.00

WALL OF DEEP END OF POOL

JUSTIFICATION: The original scope for this project was to reduce the depth of the deep end of the pool from 10 ft to 6ft and to build a new pump house. During construction, a large crack was noted at the deep corner of the pool. Parks and Recreation requested that the crack be cleaned and a primer be applied for proper adhesion, then seal the crack by injecting an epoxy into it.

1 FURNISH & INSTALL 2 @ 3 POLE 45 AMP CIRCUIT 1 LS \$3,500.00 \$3,500.00

BREAKERS AND 2 NEMA 3R 3 STARTERS.

JUSTIFICATION: The construction of the new pump house included all new filtration and pump systems. During construction the question was raised by the pool maintenance staff and the electrician that there were no starters for the pump motors. This is something that is standard on all city pools, however is not a requirement for the system to work. The starters were added to the plan by the engineer as part of the interlocking electrical system at Park and Recreation's request.

4 FURNISH & INSTALL A BENTONITE WATERSTOP IN 1 LS \$907.50 \$907.50

THE DEEP END OF POOL

JUSTIFICATION: A waterstop where the new concrete bottom meets the existing pool side was not included in the original plans. During a site visit the engineer was asked by the contractor if a waterstop was needed, which he confirmed that it was. A revised plan sheet was provided including the waterstop. The waterstop ensures that there is a water tight seal where the new and existing concrete meet.

5 FURNISH & INSTALL A BENTONITE WATERSTOP 1 LS \$4,345.00 \$4,345.00

AT BASE OF PUMP HOUSE WALLS WHERE THEY MEET

THE SLAB.

CHANGE ORDER NO. 1 6/15/2015

NET

NBR MASTER ITEM DESCRIPTION QUANTITY UOM UNIT COST ADDITION NET DELETION TOTALS

JUSTIFICATION: An RFI answer provided by the consultanting architect at the beginning of the project indicated that a waterstop was not required. During a site meeting with the Engineer, it was determined that it was needed. Based on the original RFI response, the contractor was in the process of setting up the forms to pour the wall when the site visit occurred and had to remove previously installed forms, add the water stop, and rebuild the forms. The waterstop seals the floor slab and the wall joint since the floor and walls cannot be poured at the same time.

6 LEAK DETECTION SERVICE 1 LS \$957.00 \$957.00

JUSTIFICATION: Pool was losing water after the contractor completed their work; however a different contractor was used, by Parks and Recreation, to seal and paint the inside of the pool, after which the pool continued to leak. A leak detection service was needed to determine the source of the leak, which was located in a drain line not addressed in the initial construction. If the leak detection had determined that the source was a result of work by the contractor, they would have been responsible for the leak detection. However the result was that the leak was elswhere and the contractor is to be reimbursed for the leak detection.

7 DELETE POOL BOTTOM PAINTING FROM SCOPE -1 LS \$1,605.00 (\$1,605.00)

JUSTIFICATION: Client requested that the task be removed from the contract.

8 PARKS FURNISHED AND INSTALLED A 36" 3- -1 LS \$ 2,350.00 (\$2,350.00)

STEP STAINLESS LADDER AND ELECTRICAL GROUNDING TO REPLACE LADDER MISPLACED OR STOLEN WHILE IN STORAGE.

JUSTIFICATION: This work was neessary in order for the pool to pass a Health Department final inspection required before opening the pool for public use Memorial Day 2015 weekend. The contractor either misplaced the original ladder or it was stolen while in storage. The contractor was responsible to re-install the ladder and they could not meet the deadline so the City performed the work.

TOTAL ADDITIONAL SCOPE: \$7,129.50

SUBTOTAL CHANGE ORDER NO. 1 \$16,242.50 (\$3,955.00)

NET TOTAL CHANGE ORDER NO. 1 \$12,287.50





Change Order #4 - Proposal

Project Name: Fort Caroline Pool Repairs Contract #9510-07

Scope of Work

Thank you for the opportunity to provide a proposal on this project. Should you have any questions, you may contact Kimberly directly at 904.353.1353 or email me at <u>kansley@therosearoupllc.com</u>.

Total Cost	Authorization
\$5,158.00	
Exclusions:	
_	\$5,158.00

Invoice

PARRY POOLS INC. 4571 ST. AUGUSTINE RD. JACKSONVILLE, FL 32207

Invoice #: 34732

Invoice Date: 8/18/14

Amount Remitted:

Questions? Contact us: (904) 733-7665 ... (904) 733-7946 ... information@parrypools.com

ROSE GROUP LLC 2933 N. Myrtle Ave. Jacksonville, 32209

System ID: 5466

Invoice Description: Removal concrete deck

Qty Unit Description Price Sub Total <u>Tax</u> **Total**

231 Ea Remove 5ft 6in x 42 ft of concrete deck \$20.00 \$4,620.00 \$4,620.00 **Dumpster for concrete debris**

Repair 4" PVC leak Form deck Pour concrete deck

Ea Deduction (Form and pour concrete done by others) (\$1,200.00) (\$1,200.00) (\$1,200.00

ī Testing \$738.00 \$738.00 \$738.00

Pressue testing on scum gutter line Equipment and labor

(2 days)

Invoice Amount Due: \$4,158.00 \$4,158.00





Date Invoice # 12/1/2014 Material2

Phone # 904-353-1353 Fax # 904-353-1354 kansley@therosegrouplic.com www.therosegrouplic.com

P.O. No.	Terms	Project
Pool change order 4	Net 15	





Change Order #6 - Proposal

Project Name: Fort Caroline Pool Repairs
Contract #9510-07

Scope of Work

Thank you for the apportunity to provide a proposal on this project. Should you have any questions, you may contact Kimberly directly at 904.353.1353 or email me at <u>kansley@therosegroupilc.com</u>.

Item Description	Total Cost	Authorization
Deep End Crack Clean debris from the existing cracks at the deep corner of the pool. Apply a primer for proper adhesion. Inject an epoxy on the inside of pool and the exterior	\$1,375.00	
Sub cost Labor/mtl = \$1,250.00	Exclusions:	
O/P (10%) = \$125.00		



Estimate

PARRY POOLS INC. 4571 ST. AUGUSTINE RD. JACKSONVILLE, FL 32207

Estimate #: 34470

Questions? Contact us: [Phone / Fax / Email] (904) 733-7665 ... (904) 733-7946 ... information@parrypools.com

Estimate Date: 5/21/14

ROSE GROUP LLC 2933 N. Myrtle Ave. Jacksonville, 32209 Site: ROSE GROUP LLC 2933 N. Myrtle Ave. Jacksonville, 32209

\$1,250.00

System ID: 5466

\$1,250.00

\$1,250.00

Estimate Description:

ADDITIONAL WORK

<u>Qty Unit Description</u> <u>Price Sub Total Tax Total</u>

Ea Change Order Request:

Clean debris from the existing cracks at the deep corner of the

pool

Apply a primer for proper adhesion Inject an expoxy on the inside of pool and the exterior

^{*} Epoxy to be approved by structural engineer

		Amount:	\$1,250.00	\$0.00	\$1,250.00
Submitted by and Date:	Buyer(s), Sign Acceptance, and				





Change Order #3 - Proposal

Project Name: Fort Caroline Pool Repairs
Contract #9510-07

Scope of Work

Thank you for the opportunity to provide a proposal on this project. Should you have any questions, you may contact Kimberly directly at 904.353.1353 or email me at <u>kansley@therosegroupllc.com</u>.

Item Description	Total Cost	Authorization
Electrical Interlocking	\$3,500.00	
Furnish and install		
Qty 2 – 3 pole 45 amp breakers		
Qty 2 – NEMA 3R size 3 starters		
Sub costs = \$3,500.00	Exclusions:	



Vilano Electric, Inc.

14286-19 Beach Blvd. #394 Jacksonville, Fl. 32250

Phone #	904-641-0868
Fax#	904-641-9288
vilanoe	@bellsouth.net

Estimate

Date	Estimate #
9/23/2014	5336

Name / Address		
The Rose Group Attn: Kim Ansley 2933 N. Myrtle Ave. Suite 101 Jax, FL 32209		

Project


Ft. Caroline Pool

Description		Total
Ft. Caroline Pool Change Order I		
Furnish and Install:		3,500.00
2 - 3 pole 45 amp breakers 2 - NEMA 3R size 3 starters		
Thank you for your consideration!	Total	\$3,500.00

All material is guaranteed to be as specified. All work to be completed in a workmanlike manner according to standard practices. Any alteration or deviation from above specifications involving extra costs, will be executed only upon written orders, and will become an extra charge over and above the estimate. All agreements contingent upon strikes, accidents or delays beyond our control. This proposal subject to acceptance withing days and is void thereafter at the option of the undersigned. Signature


EC0002978





Revised drawing to include new interlocking Device and starter





Change Order #7 - Proposal

Project Name: Fort Caroline Pool Repairs
Contract #9510-07

Scope of Work

Thank you for the opportunity to provide a proposal on this project. Should you have any questions, you may contact Kimberly directly at 904.353.1353 or email me at <u>kansley@therosearoupllc.com</u>.

Item Description	Total Cost	Authorization
Pool Waterstop Furnish and install bentonite waterstop (RX102) indicated in RFI #2 inside pool	\$907.50	
Labor & Mtl = \$825.00	Exclusions:	
O/P (10%) = \$82.50		



The Rose Group, LLC General Contractor

Kimberly Ansley <kansley@therosegrouplic.com>

Waterstop RX 102

 Fri, May 23, 2014 at 4:00 PM


Kimberly,

The Waterstop RX102 installed will be \$825.00 installed. This will seal the new poured concrete to the existing shell.

Thanks,

Billy

Sent from my iPhone









Change Order #8 - Proposal

Project Name: Fort Caroline Pool Repairs
Contract #9510-07

Scope of Work

Thank you for the opportunity to provide a proposal on this project. Should you have any questions, you may contact Kimberly directly at 904.353.1353 or email me at <u>kansley@therosegroupllc.com</u>.

Item Description	Total Cost	Authorization
Pumphouse Waterstop Furnish and install bentonite waterstop. RFI #2 response indicated no waterstop was required or needed. On 6/24/14, structural engineer required bentonite waterstop. Price includes • removal of forms previously erected • re-install forms, clean debris • waterstop material • weekend labor	\$4,345.00	
Labor = \$3,000.00	Exclusions:	
Material = \$950.00		
O/P (10%) = \$395.00		

. PREIC WORKS



Jacks nville Where Florida Begins.

REQUEST FOR INFORMATION (RFI)

PROJECT: Ft. Caroline Pool Repair	DATE:	3/11/14
	RFI #or NOI	#: #2
CONTRACTOR: The Rose Group	SPEC REF:	
CONTRACT/P.O. #: 9510-07	DWG REF:	A102 and AS-101
RFI or NOI SUBJECT: Waterstop and paint finish		
RFI or NOI DESCRIPTION:		<u> </u>
1 Section 2/A102 does not show any water stop at the joints in the concrete. Please advise if intri water stop is re-	equired. If so, plause Indicate	the required location and the type of product that is to be used.
2. Please confirm that a paint finished is required on the bottom an	d sides of the nev	v pool slab, and not aggregate finish.
SUBMITTED BY: Kim Ansley		
Contractor's Representative		
	lla aam	
REQUEST REPLY BY: Email: kansley@therosegroup	olic.com	
REPTY ARUMTRUTURAL DRAWINGS CA	11. 50	POOL TO HAVE PAINT
n in the second		
PINISH AND STRIPES TO MATCH		The second secon
TANK IS TO HAVE HOGREGATE	. FINISH	
AT WATER STOPS ARE NOT K	COROCA	ON PENITREN
I MILES STOTO THEE HAT IN	(C) (T) (D)	of Russific,
1		
REPLY BY:	DATE:	1 Agen 2014
Owner's Henresentative	DC 15.	

This reply does not necessarily constitute an increase in contract value or time. Any Change in contract value or time will require supplemental information submitted by the contractor for review and approval.

214 N Flogan Street, 10th Floor | Tacksonville, FL 12202 | Phone 904 255-8755 | Fax 904 255-8913 | www.coj.net





ATLANTIC ENGINEERING SERVICES

SITE VISIT REPORT

6501 Arlington Expy.
Building B, Suite 201
Jacksonville, F£ 32211
PH: 904.743.4633
FX: 904.725.9295
jax@aespj.com
www.aespj.com

July 2, 2014

SITE VISIT REPORT NO. 03

PROJECT NAME

Fort Caroline Community Center - Pool Rehabilitation and Equipment Enclosure

PROJECT NO. 309-208.01

DATE OF SITE VISIT

July 2, 2014

TIME

12:30 pm

PRESENT AT SITE

Mr. Steve Newsome

The Rose Group, LLC

Mr. Mark J. Keister, P.E.

Atlantic Engineering Services (AES)

DISTRIBUTION:

Ms. Kimberly Ansley

The Rose Group, LLC

Mr. Stephen F. Lazar, AIA, LEED AP

VRL Architects, Inc.

The purpose of our visit to the site of the above referenced project was to observe the progress of construction to date. The following items were observed and/or discussed at the site:

- 1) The pump building reinforcing is in place at the pump room and the water tank. At the pump room, the wall reinforcing is in place according to the documents, except for the roof dowels that are in line with the wall. Just prior to concrete placement, rotate the roof dowels into the proper position.
- 2) The majority of the tank reinforcing is in place. Opening additional vertical, horizontal and diagonal reinforcing has not been placed yet. At the wall construction joint, provide a Class "B" lap for all horizontal bars on either side of the joint.
- 3) At the base of all walls, a key has been formed and a bentonite waterstop will be placed, just prior to concrete placement.
- 4) Prior to concrete placement, clean forms free of debris.

Please call if there are any questions regarding this correspondence.

Submitted by:

ATLANTIC ENGINEERING SERVICES OF JACKSONVILLE FLORIDA CERTIFICATE OF AUTHORIZATION #791

Mark J. Kerster, P.E.

Principal

MJK/drg



Line & Grade Contracting, LLC

3426 Devilwood Street Middleburg, FL 32068

10					=		
	14	١,		$\overline{}$		\sim	$\overline{}$
		יו	v	0	•	4 =	ᆫ
•	•		7	•	•	•	J

Date	Invoice#
7/15/2014	12444

BillTo	
The Rose Group 2933 N. Myrtle Ave. Ste. 101 Jacksonville, FL 32209	

P.O.No.	Terms	Project	
	Due on receipt	Ft. Carolina Community Ce	

Quantity	Description	Rate	Amount
	Pool Pump House additional weekend labor for wall pour 10 hours each day (Saturday 7/12 and Sunday 7/13) 7 man crew, \$2,450/day	4900.00	4,900.0
	₩		
		Total	

Labor was reduced do





oc Group, LLC The Rose Group, LLC

Suite 101 Jacksonville, FL 32209

Phone # 904-353-1353 kansley@therosegroupllc.com
Fax # 904-353-1354 www.therosegroupllc.com

Date	Invoice#
7/11/2014	Materials

Bill To	
City of Jacksonville 117 W. Duval Street Suite 335 Jacksonville, FL 32202	

P.O. No.	Terms	Project
Pool Change order	Net 15	Fort Caroline Pool

Quantity	Description	U/M	Rate	Amount
	Waterstop materials purchased for the Fort Caroline Pool change order from Coastal Construction products		950.00	950.00
	·			
			Total	\$950.0





Change Order #11 - Proposal

Project Name: Fort Caroline Pool Repairs
Contract #9510-07

Scope of Work

Thank you for the opportunity to provide a proposal on this project. Should you have any questions, you may contact Kimberly directly at 904.353.1353 or email me at $\underline{kansley@theroseqrouplic.com}$

Item Description	Total Cost	Authorization
Leak Detection Service To identify why the pool is losing water. It was discovered there is a leak in the existing plumbing line of the scum gutter, which was not part of the scope of work.	\$ 957.00	
Subcontractor Costs = \$870.00	Exclusions:	
Contractor OH/P = \$87.00		



American Leak Detection - Jacksonville

11076 Blue Roan Ct Jacksonville, FL 32257



Invoice

Phone #

904-519-5700

Fax # 904-519-2929

HE ORIGINAL TOAK SPECIALISTS

Date	Invoice #
2/10/2015	JAX-02871

Bill To

The Rose Group 2933 N. Myrtle Ave Suite 101 Jacksonville, FL 32209 USA Site Location

4131 Ferber Rd Jacksonville, FL 32277 USA

Tech	Claim Number	Terms
DT		

Item	Description	Amour	nt
	1/29 - This is a 6 lane olympic size commercial pool with 28 scum cups. Pool has gone thru major renovations. Pump room was at same level as pool untill it sank down the hill. Pump room is now at bottom of hill. Deep end was filled with 4ft of concrete, pool was completly refinished and when filled for first time found it to be leaking. After much difficulty pressure tested return line(16 wall returns) and it holds pressure. With returns plugged leakvue is showing large loss in pool and /or holding tank. Running out of daylight. Will return to complete detection. Closed all valves to isolate 4ft x 10ft x 12ft deep holding tank from pool to run static test on pool and tank. 2/10 - Pool is at about the level as when I left. Dove pool to test and inspect structure and bottom drain area and found no problems. With pool isolated from tank leakvue shows no loss. Tank however has dropped about 2ft. Dove tank and found large gaps on the bottom of most of the ladder rungs, repaired with epoxy. Rest of tank looked ok. After repairs marked water level in tank to run static test. Tried to fill scum gutter plumbing and shelf with water to run static test and it won't hold water. Plugged all 28 scum cups and using electronic equip. while inducing air, located and marked break in scum gutter plumbing under deck near side of pool at end of pool in front of pump house. With scum cups plugged, scum shelf seems to be holding water. After repairs in tank, static test shows no loss in tank.		
1	Commercial pool with 28 scum cups		870.0
1	Commercial Epoxy Repair		40.0

Guarantee on Detections - All Leak locations and detection work is quaranteed for 30 days from the date of completeion. We will re-test the system or refund the detection fee (at our option) if is is reported within the above 30 day period that a leak still exists. We will not be liable for any consequential losses.

Total \$910.00

Guarantee On Repairs - Minor repairs made by American Leak Detection are guaranteed for 30 days. Major repairs are guaranteed for 12 months. All repairs are guaranteed from the date of completion and for defective workmanship only.

Email - jacksonville@americanleak.com

Web Site - www.americanleak.com





Change Order #9 - Proposal

Project Name: Fort Caroline Pool Repairs
Contract #9510-07

Scope of Work

Thank you for the opportunity to provide a proposal on this project. Should you have any questions, you may contact Kimberly directly at 904.353.1353 or email me at kansley@therosegrouplic.com

Item Description	Total Cost	Authorization
Credit for Pool Painting	\$1,605.00	
Credit to COJ for painting	CREDIT	
8 gallons @ \$125/gallon		
Labor = \$500.00	Exclusions:	
Material = \$1,000.00		
O/P (10%) = \$105.00		



Purchase Order



City of Jackson ville 214 N. Hogan Street, Suite 800 Jacksonville, Fi= 32202

Vendor Number: 00010771
NE Backyard Designs, Inc
De 4265-A Eldridge Loop
Oa Orange Park, FL 32073
Phone No: 904-272-9473

PO Date: 06/05/2015

Buyer: Ivy Posev Phone #: (904) 255 - 8816

FOB: F.O.B., Destination Terms: Net 30

Purchase Order Number

Purchase Ordes

ALE PACKING SLIPS INVOICES.

AND CORRESPONDENCE MUST
REFERENCE THIS NUMBER:

Parks, Recreation & Community Srvs
Harmonic Office of Director
214 N. Hogan Street
4th Floor
Jacksonville, FL 32202
Office of Director

± 5 6 ±

Finance Services Department Accounts Payable 117 W. Duval Street, Suite 375 Jacksonville, FL 32202

Pa	Department rks, Recreation & Community Srvs	Bid Number		quisition EQ1711		Delivery Date 06/20/2015
ltem	Des	cription	Quantity	Unit	Unit Price	Total
1	WORK TO BE DONE AT FT CAROLINE PROVIDE AND INSTALL 36" 3 STEP EQUIPMENT ROOM	PARK LADDER AND RUN GROUND WIRE TO	1.00	EA	\$2,350.00	\$2,350.0
	LN / FY / Account Code	Dollar Amount				
	1 / 15 / RPCP31OF5720-06505PR0597	-01				
ļ				!		
						i
į					Subtotal: Freight: Discount:	\$2,350. \$0. \$0.
				•	TOTAL:	\$2,350.

THIS ORDER IS SUBJECT TO THE GENERAL CONDITIONS ATTACHED HERETO.

MANUFACTURER'S FEDERAL EXCISE TAX EXEMPT NO: 59-89-0120K

FLORIDA STATE SALES AND USE TAX EXEMPTION NO: 85-8012521607C-8

Revised Date: 01/14/2008

Approved By Gregory Pease, Chief
Procurement Division

May Perm





4265-A Eldridge Loop Orange Park, FL 32073

Phone (904) 272-9473

Fax (904) 644-8780

Invoice

15-1866

6/3/2015

- Bilk Tox
Finance Services Department
Accounts Payable
117 W. Duval Street, Suite 375
Jacksonville, FL 32202

Due Date 6/3/2015

Description	Amount
Vendor - 00010771	
Jobsite: Ft. Caroline Pool	
Provide and install 36" 3-step ladder and run ground wire to equipment room as required by the Department of Health	2,350.00

Total	\$2,350.00
Payments/Credits	\$0.00
Balance Due	\$2,350.00